



## **Tech-B5: Ford/Mercury Release Bearing & Steel Repair Sleeve Kit**

**Application:** 1988–1990 Ford Escort, Tempo Taurus (including SHO) and Mercury Sable & Topaz with the MTX manual transmission.

**Kits:** 07-069, 07-078

**The Problem:** Excessive wear on the release bearing retainer (quill).

**The Solution:** Steel Retainer Sleeve that gives the release bearing a new surface to slide on.

Ford released part number F2DFZ7548 consisting of a release bearing and steel sleeve. These parts are designed to replace the O.E. bearing and repair the damaged retainer bearing collar quill on the above mentioned applications with the MTX manual transmission.

